

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken.....

None

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

Immediate repairs of the
damaged portion of the pipelines.
Security should be intensified.

12. Time investigation ended.....

2:56 PM

13. Name and Signature of Participants