

INCIDENT NO : 3858633



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: Shell Petroleum Development Company

2. Type of Complaint/Incident:

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☒ Others (Specify) Asset Damage

3. Incident Details

i. Date of Incident: 25/10/24 ii. Date first reported: 26/10/2024

iii. Date of first investigation: 12/12/2024

iv. Date of follow-up investigation: N/A

v. Time investigation started: 12:55 HRS

vi. Estimated quantity spilled: No spill

4. Site Details

i. Site/Location: 16" Ogale - Ebubu T/L at Obolo

ii. Position of Spill/Leak: 4° 46' 58.89" N 7° 7' 56.66" E

iii. Spill area

☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (specify) No spill

iv. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) /

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock

☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (specify) None

iii. Facility

☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant ☐ Others (specify) /

iv. Cause Of Spill

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (specify) /

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☒ Others (specify) 1.5" galvanised pipe attached to a 1.5" valve installed at 12 O'clock position on the 6" pipeline

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify) *.....*

ii. Nature of Impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others *..... 1st impact*

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. *.....*
 ii. *.....*
 iii. *.....*
 iv. *.....*

b) Land (indicate area in m²)

- i. *.....*
 ii. *.....*
 iii. *.....*
 iv. *.....*

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>
<i>.....</i>	<i>.....</i>	<i>.....</i>	<i>.....</i>

8. Photography a/c/Mapt. best Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken

1/10/02

10. Investigation carried out by

☒ WFO ☐ BMD ☐ MMSA

11. Remarks/Recommendation

Immediate repairs to the damaged portion of the pipeline security should be intensified

12. Time investigation ended

13/4/2002

13. Name and Signature of Watchman