

20. Photographs:



Fig 1. Showing the incident point after excavation.



Fig 2. Showing point after repair.