



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Seplat Energy Producing Nigeria Unltd.	
Reporting Officer		John Itsueli	
Designation		General Manager Joint Venture Operation	
Phone Number		0817 207 3917	
Email Address		jitsueli@seplatenergy.com	
Incident Number		001/ 2025	
Section 2 - Location			
State / LGA		QIT / Ibeno	
Coordinates of spill		EASTINGS 4Deg 32Min/37Secs N NORTHINGS 8Deg 1Min/11Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☐ Offshore ☐ Subsea ☐ Swamp Area ☒ Others	
Depth of Water (if applicable)		Not Applicable (NA)	
Section 3 – Spill Details			
Date and Time of spill		2/5/2025 Time: 15:55 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☒ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Equipment failure: During crude loading (export) activity, company personnel observed a leak from the Condensate Metering Skid Prover Loop door in QIT. The prover loop door seal failure was suspected.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☒ Bund wall ☒ Sorbent ☐ Others (specify).....	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type	NA	NA
	SG/API Gravity	NA	NA
	Pour Point	NA	NA

	Wax Content	NA	NA
	Asphaltene	NA	NA
	Sulphur Content	NA	NA
	Viscosity	NA	NA
Oil	Slick Locations(s)	NA	NA
observation	Slick Dimension(s)	NA	NA
	Orientation of slick(s)	NA	NA
	Distribution of oil	NA	NA
	Obvious odour	NA	NA
Oil descriptions	Tarballs (tb)	NA	NA
	Convergence line (co)	NA	NA
	No structure (ns)	NA	NA
	Windrows (wr)	NA	NA
	Streamers (st)	NA	NA
	Patches (pa)	NA	NA
Oil color and appearance	Silver/grey	NA	NA
	Rainbow	NA	NA
	Metallic	NA	NA
	Transitional	NA	NA
	Dark	NA	NA
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☒ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release		Continuous Release
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.5 bbl of crude oil released to concrete surface (based on recovered volume)	
	Coverage		
	Direction of travel		
Section 5 - Weather			
METEOROLOGICAL DATA			NIMET weather forecast
Wind Direction (wind direction given from)			
Initial Wind Speed			
Air Temperature (C or OF)			
Visibility Estimate		☒ Good ☐ Fair ☐ Poor	
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood		High ☐ Ebb ☐	
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning		Yes ☐	No ☐
Recovery of free phase oil		Yes ☒	No ☐
Booming		Yes ☐	No ☐
Wild life rehabilitation		Yes ☐	No ☐
Dispersant application		Yes ☐	No ☐
Section 6 – Pre-Entry Activities			


Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	-------------------------------------	---	---

Additional information (please use start date and time)
Export activity was suspended, and spill recovered completely. Plans ongoing to replace faulty seal and resume crude oil loading activity.

Section 8– Equipment	
On Site	

REPORTING OFFICER: John Itsueli
DESIGNATION: General Manager, Joint Venture Operations

Initial
FBU

Signed by:


SIGNATURE:31AFB6B4837644A.....

06-Feb-25 | 21:19 WAT
DATE:

*RBA Report must be submitted within 24 Hours of the Spill Incidence.