



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Seplat Energy Producing Nigeria Unltd.	
Reporting Officer		John Itsueli	
Designation		General Manager Joint Venture Operation	
Phone Number		0817 207 3917	
Email Address		jitsueli@seplatenergy.com	
Incident Number		005/ 2025	
Section 2 - Location			
State / LGA		Ekpe PP / OML 70	
Coordinates of spill		4° 16.70'N, 8° 12.27'E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)		Not Applicable (NA)	
Section 3 – Spill Details			
Date and Time of spill		3/9/2025 Time: ~1700 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES	
		☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline	
		PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line	
		STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify).....	
		PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Equipment failure: During the installation of MOL Pump B1, small discharge of oily water from the suction line was observed due to an overfilled pump skid.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify): Emergency Shut down activated and the leak stopped immediately.	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type	NA	NA
	SG/API Gravity	NA	NA
	Pour Point	NA	NA
	Wax Content	NA	NA
	Asphaltene	NA	NA
	Sulphur Content	NA	NA
	Viscosity	NA	NA
Oil	Slick Locations(s)	NA	NA
observation	Slick Dimension(s)	NA	NA

Oil descriptions	Orientation of slick(s)	NA	NA
	Distribution of oil	NA	NA
	Obvious odour	NA	NA
	Tarballs (tb)	NA	NA
	Convergence line (co)	NA	NA
	No structure (ns)	NA	NA
	Windrows (wr)	NA	NA
	Streamers (st)	NA	NA
Oil color and appearance	Patches (pa)	NA	NA
	Silver/grey	NA	NA
	Rainbow	NA	NA
	Metallic	NA	NA
	Transitional	NA	NA
Dark	NA	NA	
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☒ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release		Continuous Release
			Per Hour ☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.000017bbl of oily water based on sheen appearance	
	Coverage	About 4m x 2m of 60% rainbow colors and 40% silvery sheen on the sea	
	Direction of travel	North	
Section 5 - Weather			
METEOROLOGICAL DATA			NIMET weather forecast
Wind Direction (wind direction given from)	North		
Initial Wind Speed	12 knots		
Air Temperature (C or OF)	20°C		
Visibility Estimate	☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood	High ☐ Ebb ☐		
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning	Yes ☐	No ☐	
Recovery of free phase oil	Yes ☐	No ☐	
Booming	Yes ☐	No ☐	
Wildlife rehabilitation	Yes ☐	No ☐	
Dispersant application	Yes ☐	No ☐	
Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐

Additional information (please use start date and time)
Emergency shut down was activated and the leak stopped immediately. Blind flange was re-installed on the MOL Pump B1 suction header.


Section 8– Equipment	
On Site	

REPORTING OFFICER: John Itsueli
DESIGNATION: General Manager, Joint Venture Operations

Initial

Pl

Signed by:



31AFB6B4837644A...

10-Mar-25 | 15:47 WAT

SIGNATURE: **DATE:**

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*