



INCIDENT NO: 000023

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: RENAISSANCE AFRICA ENERGY COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 28/4/2025 ii. Date first reported: 28/4/2025
iii. Date of first investigation: 30/4/2025
iv. Date of follow-up investigation:
v. Time investigation started: 4:42 PM
vi. Estimated quantity spilled: 15 BBL RECOVERED 12 BBL

4. Site Details

- i. Site/Location: 10" DIEBU CREEK - NUN RIVER PIPELINE @ OPOROMA
ii. Position of Spill/Leak: N 4° 48' 20.8" E 6° 6' 38.8"
iii. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☒ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☐ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☐ Theft ☒ Acid
☒ Others (Specify)

100mm LONG HACKSAW CUT AT 3 O'CLOCK POSITION WAS OBSERVED AS AT THE TIME OF JIV ON THE PIPELINE.

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
- ☒ Fish Pond
- ☒ Vegetation
- ☒ Fishing Net
- ☒ Surface water
- ☒ Venerable Objects
- ☒ Others (Specify) SOIL

ii. Nature of impact

- ☒ Oil stained vegetation
- ☒ Oil stained fishing nets
- ☒ Dead floating fishes
- ☒ Dead floating crabs
- ☒ Withering of vegetation
- ☒ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
- ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i. OPOROMA
- ii.
- iii.
- iv.

(b) Land (Indicate area in m²)

- i. 0.0015 Ha
- ii.
- iii.
- iv.

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... NO

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation (1) IMMEDIATE CLEAN UP OF THE CRUDE OIL IMPACTED
ENVIRONMENT DUTY MONITORED BY NOSDRA. (2) SURVEILLANCE SHOULD BE
INTENSIFIED BY THE COMPANY.

12. Time Investigation ended..... 5:15 PM

13. Name of Investigator.....