



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: RENAISSANCE AFRICA ENERGY COMPANY LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution      ☒ Fire/Explosion      ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) \_\_\_\_\_

3. Incident Details

- i. Date of Incident: 23/07/2026      ii. Date first reported: 23/07/2026  
iii. Date of first investigation: 28/07/2026  
iv. Date of follow-up investigation: \_\_\_\_\_  
v. Time investigation started: 12:49 HRS  
vi. Estimated quantity spilled: 1.621 HA / 88 BARRELS

4. Site Details

- i. Site/Location: 10<sup>th</sup> DIBBU CREEK-NUN RIVER DELIVERY LINE RIGHT ENIWARI  
ii. Position of Spill/Leak: 4-75230      6-10277

iii. Spill area

- ☒ Land      ☒ Swamp      ☒ Freshwater      ☒ Mangrove      ☒ Coastline  
☒ Near shore      ☒ Offshore      ☒ Others (Specify) \_\_\_\_\_

iv. Structural Controls in Place

- ☒ Boom      ☒ Trenches      ☒ Bund Wall      ☒ Sorbents      ☒ Others (Specify) \_\_\_\_\_

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock      ☒ 10 O'Clock      ☒ 2 O'Clock      ☒ 3 O'Clock  
☒ 4 O'Clock      ☒ 5 O'Clock      ☒ 6 O'Clock      ☒ 9 O'Clock to 30'clock

ii. Type of Oil Contaminant

- ☒ Crude Oil      ☒ Condensate      ☒ Chemicals      ☒ Refined Products  
☒ Others (Specify) \_\_\_\_\_

iii. Facility

- ☒ Pipeline      ☒ Flow Line      ☒ Wellhead      ☒ Manifold      ☒ Flow Station      ☒ Rig  
☒ Storage Tank      ☒ Compressor Plant  
☒ Others (Specify) \_\_\_\_\_

iv. Cause of Spill

- ☒ Corrosion      ☒ Equipment Failure      ☒ Third Party Interference      ☒ Accident  
☒ Operational Error      ☒ Others (Specify) \_\_\_\_\_

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks      ☒ Drilled Holes      ☒ Blasting      ☒ Theft      ☒ Acid  
☒ Others (Specify) \_\_\_\_\_

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
 ☒ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
 Dead floating crabs  
 Withering of vegetation  
 Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW  
 ☒ Outside Company's facility/ROW

## 7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m<sup>2</sup>)

- i. ENIWARA ..... i. 1.621 ha .....  
 ii. .... ii. ....  
 iii. .... iii. ....  
 iv. .... iv. ....

(c) Creek/Creek lets

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

9. Samples taken: .....

10. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

11. Remarks/Recommendation RENAISSANCE SHOULD CLEAN UP THE IMPACTED AREA IMMEDIATELY AND REPAIR THE AFFECTED FACILITY. RENAISSANCE SHOULD IMPROVE SURVEILLANCE ON ITS FACILITIES/ASSETS TO PREVENT THIRD PARTY INTERFERENCE.

12. Time Investigation ended 14:57 HRS. ....