NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
   - [✓] Oil Pollution [X] Fire/Explosion [X] Drilling Mud/Chemical Pollution
   - [X] Others (Specify).....
3. Incident Details
   - i. Date of Incident: 18/06/2022 ii. Date first reported: 18/06/2022
   - iii. Date of first investigation: 18/06/2022 iv. Spill Incident No: 2022/LAR/071
   - v. Date of follow-up investigation: ...../...../.....
   - vi. Time investigation started: 1147 HRS
   - vii. Estimated quantity spilled(bbls): 5.32 viii. Quantity Recovered: NIL
4. Site Details
   - i. Site/Location: 6" THOMO-OGBOINBIRI PPL @ AYAMASA
   - ii. State: BAYELSA iii. L.G.A: EKEREMOR
   - iv. Spill Co-Ordinates: N(m) 05°07' 04.2" E(m) 005°54' 28.6"
   - v. Spill area
     - [✓] Land [X] Swamp [X] Freshwater [X] Mangrove [X] Coastline
     - [X] Near shore [X] Offshore [X] Others (specify).....
   - iv. Structural Controls in Place
     - [X] Boom [X] Trenches [X] Bund wall [X] Sorbents [X] Others (specify).....
5. Circumstances Around Spill Point
   - i. Visual observation of Hole Position
     - [X] 12 O' Clock [X] 10 O' Clock [✓] 2 O' Clock [✓] 3 O' Clock
     - [✓] 4 O' Clock [✓] 5 O' Clock [✓] 6 O' Clock (2 - 6 O'Clock)
   - ii. Type of Oil contaminant
     - [X] Crude Oil [✓] Condensate [X] Chemicals [X] Refined Products
     - [X] Others (specify) .....
   - iii. Facility
     - [✓] Pipeline [X] Flow line [X] Wellhead [X] Manifold [X] Flow Station [X] Rig
     - [X] Storage Tank [X] Compressor Plant [X] Others (specify).....
   - iv. Cause of Spill
     - [X] Corrosion [X] Equipment Failure [✓] Third Party Interference [X] Accident
     - [X] Operational Error [X] Others (specify).....
   - v. Visible Sign of Third Party Interference
     - [✓] Hacksaw Marks [X] Drilled Holes [X] Blasting [X] Theft [X] Acid
     - [X] Others (specify).....

6. Impact of Incident

i. **Properties impacted by the incident**

☒Farmland ☒Fish Pond ☑Vegetation ☒Fishing Net ☒Surface water

☒Venerable Objects ☒Others (specify).....

ii. **Nature of impact**

☑Oil stained vegetation ☒Oil stained fishing nets ☒Dead floating fishes

☒Dead floating crabs ☒Withering of vegetation ☒Others.....

iii. **Delineation of impacted area**

☑Within Company's facility/ROW ☒Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift

☒ Permanent ☒ Others .....

8. Extent of Impact

a) Community (*indicate name*)

i. .....

ii. .....

iii. .....

iv. .....

b) Land (*indicate area in m^2*)

i. .....

ii. .....

iii. .....

iv. .....

b) Creeks/Creek lets ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.
   ☑ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken.....

11. Investigation carried out by
    ☑ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation.....

.....

.....

13. Time investigation ended.....

14. Name and Signature of Participants

- NOSDRA
  1. LIKAM UKIEN EKUP 18/06/2022
  2.
  3.

- DPR
  1.
  2.
  3.

- STATE MINISTRY OF ENVIRONMENT
  1. Lucky Joses 18/6/22
  2.
  3.

- COMPANY
  1. Akporugo Festus.E. NAOC (ITSE)
  2. Emeka.O NAOC CRL
  3. C.N. Aduwe NAOC SXD
  4.
  5.

- COMMUNITY
  1. DUKE TARE, CDC Chairman Ayamasa
  2.
  3.
  4.
  5.