2024/LAR/049

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. **Company:** NAOC

2. **Type of Complaint/Incident:**

☑ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify) .....

3. **Incident Details**

i. Date of Incident: 13/6/2024 ii. Date first reported: 13/6/2024

iii. Date of first investigation: 24/6/2024

iv. Date of follow-up investigation: .....

v. Time investigation started: 15:05 HRS

vi. Estimated quantity spilled: 49 bbls Recovered 37.74bbls

4. **Site Details**

i. Site/Location: 4" Ngbede 17T Flowline @ Okwuzi Oneigu LGA Rivers state.

ii. Position of Spill/Leak: N05° 29' 35.4" E006° 43' 08.0"

iii. **Spill area**

☑ Land ☐ Swamp ☑ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify) .....

iv. **Structural Controls in Place**

☑ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify).....

5. ***Circumstances Around Spill Point***

i. **Visual observation of Hole Position**

☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock

☐ 4 0'Clock ☐ 5 0'Clock ☑ 6 0'Clock

ii. **Type of Oil Contaminant**

☑ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (Specify) .....

iii. **Facility**

☑ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify) .....

iv. **Cause of Spill**

☐ Corrosion ☐ Equipment Failure ☑ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify) Leak from third party weld point.

v. **Visible Sign of Third Party Interference**

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☑ Theft ☐ Acid

☐ Others (Specify) .....

CamScanner

6. Impact of Incident

i. Properties Impacted by the Incident

☑ Farmland ☐ Fish Pond ☑ Vegetation ☒ Fishing Net ☒ Surface water

☒ Venerable Objects ☒ Others (Specify) .....

ii. Nature of impact

☑ Oil stained vegetation ☒ Oil stained fishing nets ☑ Dead floating fishes

☒ Dead floating crabs ☑ Withering of vegetation ☒ Others (Specify) .....

iii. Delineation of Impacted area

☑ Within Company's facility/ROW ☑ Outside Company's facility/ROW

7. Extent of Impact

(a) Community *(Indicate name)*

i. OKWUZI

ii. ABAEZI

iii. .....

iv. .....

(b) Land *(Indicate area in m^2)*

i. 581.00

ii. .....

iii. .....

iv. .....

(c) Creek/Creek lets ☐ *Tidal* ☐ *Non-tidal*

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

CamScanner

8. Photograph/Map/Chart Ref.

☑ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken None.

10. Investigation carried out by

☑ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation NOSDRA mandated NAOC to carry-out repairs on the line immediately. NAOC should clean-up the area impacted within two weeks from date of INV. NAOC should enhance surveillance on its facility.

12. Time Investigation ended 16:03 HRS.

CamScanner