NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. **Company:** Oando — 2026/IAP/030

2. **Type of Complaint/Incident:**

☑ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify) .....

3. **Incident Details**

i. Date of Incident: 05-10-2026 ii. Date first reported: 05-10-2026.

iii. Date of first investigation: 06-10-2026.

iv. Date of follow-up investigation: —

v. Time investigation started: 12:35 Hrs.

vi. Estimated quantity spilled: 0.136bl

4. **Site Details**

i. Site/Location: 18" Ebocha - Oando PLC mobile Onedge.

ii. Position of Spill/Leak: N05° 26' 05.74" E006° 44' 31.65"

iii. **Spill area**

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (Specify).....

iv. **Structural Controls in Place**

☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify).....

5. **Circumstances Around Spill Point**

i. **Visual observation of Hole Position**

☑ 12 0'Clock ☒ 10 0'Clock ☒ 2 0'Clock ☒ 3 0'Clock

☒ 4 0'Clock ☒ 5 0'Clock ☒ 6 0'Clock

ii. **Type of Oil Contaminant**

☑ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (Specify) .....

iii. **Facility**

☑ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant

☒ Others (Specify) .....

iv. **Cause of Spill**

☒ Corrosion ☒ Equipment Failure ☑ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (Specify) .....

v. **Visible Sign of Third Party Interference**

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☑ Theft ☐ Acid

☑ Others (Specify) 2" Ball Valve Seam of Faulty Pipeline

6. **Impact of Incident**

i. **Properties Impacted by the incident**

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☑ Surface water

☒ Venerable Objects ☐ Others (Specify) .....

ii. **Nature of impact**

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes

☒ Dead floating crabs ☒ Withering of vegetation ☒ Others (Specify) .....

iii. **Delineation of Impacted area**

☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. **Extent of Impact**

(a) **Community** (*Indicate name*)

i. Mobile Community

ii. .....

iii. .....

iv. .....

(b) **Land** (*Indicate area in m²*)

i. 78.53m²

ii. .....

iii. .....

iv. .....

(c) **Creek/Creek lets** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) **Swamp** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) **River** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) **Shoreline/water** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

CamScanner

2026/LAD/030

18" Ebocha — Ogba pipeline may be de comm

8. **Photograph/Map/Chart Ref.**

☑ Still photographs ☒ Video coverage ☒ Mapping

9. **Samples taken**..... None as at the time of JIV

10. **Investigation carried out by**

☑ Foot ☒ Boat ☒ Aircraft

11. **Remarks/Recommendation**... Repairs was advised immediately, Mopped up of the Crude around the bund wall was also advised to be carried out.

12. **Time Investigation ended** 07:45 Hrs