NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. **Company:** NIGERIAN AGIP OIL COMPANY

2. **Type of Complaint/Incident:**

☑ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify) .....

3. **Incident Details**

i. Date of Incident: 20-11-2022 ii. Date first reported: 20-11-2022

iii. Date of first investigation: 21-11-2022

iv. Date of follow-up investigation: /

v. Time investigation started: 14:01HRS

vi. Estimated quantity spilled: 9.7BBLS

4. **Site Details** 18" EOC/OGOBA PIPELINE AT UBETA MBOADE W/LGA

i. Site/Location .....

ii. Position of Spill/Leak: N05°09'503" E006°35'156 .....

iii. **Spill area**

☑ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify) .....

iv. **Structural Controls in Place**

☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) .....

5. **Circumstances Around Spill Point**

i. **Visual observation of Hole Position** 1-3 o'clock

☐ 12 0'Clock ☑ 1 0'Clock ☑ 2 0'Clock ☑ 3 0'Clock

☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. **Type of Oil Contaminant**

☑ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (Specify) .....

iii. **Facility**

☑ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify) .....

iv. **Cause of Spill**

☐ Corrosion ☐ Equipment Failure ☑ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify) .....

v. **Visible Sign of Third Party Interference**

☑ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (Specify) .....

CamScanner

i. Properties Impacted by the incident

☑ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects ☐ Others (Specify) .....

ii. Nature of impact

☑ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) .....

iii. Delineation of Impacted area

☑ Within Company's facility/ROW ☑ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (*Indicate name*)

i. UBETA

ii. .....

iii. .....

iv. .....

(b) Land (*Indicate area in m^2*)

i. 853.65 m^2

ii. .....

iii. .....

iv. .....

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

CamScanner

8. **Photograph/Map/Chart Ref.**

☑ Still photographs ☐ Video coverage ☐ Mapping

9. **Samples taken**..... NIL .....

10. **Investigation carried out by**

☑ Foot ☐ Boat ☐ Aircraft

11. **Remarks/Recommendation**..... NADC Should Carryout repairs on the
- NADC Should, Improve on the security/Surveilla
- NADC Should clean up and remediate the Impacte

12. **Time Investigation ended**..... 14:35HRS .....

CamScanner