

ID: ~~t1646~~ / 15055



Spill ID: 128394 ^{BL}

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: National Pipeline and Storage Company (NPSC)

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 11/12/2017 ii. Date first reported: 13/12/2017
iii. Date of first investigation: 14/12/2017
iv. Date of follow-up investigation:
v. Time investigation started: 1340 Hrs
vi. Estimated quantity spilled: 5 bbl

4. Site Details

- i. Site/Location: System 2C Abaji Axis, Km 77.4, Whugu
ii. Position of Spill/Leak: N 08° 41' 56.6" E 006° 55' 9.67", Z 119m
iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify) Stream

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) Pegged hole (de)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☒ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) It was alleged to be third party

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) interference by the NPSC.

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) *Oil Sheen on the stream*

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

- ☐ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken... NIL

10. Investigation carried out by



- ☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation Clean-up / Remediation of impacted ^{site} should be carry out immediately, Security Surveillance should be improved, and Containment Boom should deployed in the stream.

12. Time Investigation ended... 1430 Hrs

13. Name and Signature of Participants

❖ NOSDRA

1. Siyaka Aminu 
2. Fatima Agumchi 
3.

❖ DPR

1.
2.
3.


❖ STATE MINISTRY OF ENVIRONMENT

1.
2.
3.

❖ LOCAL GOVERNMENT COUNCIL

1.
2.
3.

❖ COMPANY

1. NPSC / ABASI PUMP STATION
2. GOMNA, M. A. / GMA
3. Yahaya A. A. 

❖ COMMUNITY

1.
2.
3.