

445340



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY **JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
 - ☒ Others (Specify) GAS
3. Incident Details
 - i. Date of Incident: 26/06/18 ii. Date first reported: 26/06/2018
 - iii. Date of first investigation: 27/06/18 iv. Spill Incident No: 2018/SK/003
 - v. Date of follow-up investigation: NIL
 - vi. Time investigation started: 9:10 HRS
 - vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: 6" TYOMD - OGBOMIRI GAS DELIVERY LINE AT KASSAMA.
 - ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW LGA
 - iv. Spill Co-Ordinates: N(m) 04°53'01.8" / 04°52'59.71"
E(m) 005°56'47.3" / 005°56'49.70"
 - v. Spill area
 - ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
 - ☒ Near shore ☒ Offshore ☒ Others (specify)
 - iv. Structural Controls in Place
 - ☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify) NONE
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position THE PIPE WAS CUT AT 2 POINTS OF 0-7m APART.
 - ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock POINT A = 8-11 O'CLOCK POSITION
 - POINT B = 1-4 O'CLOCK POSITION
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
 - ☒ Others (specify) NONE
 - iii. Facility
 - ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
 - ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)
 - iv. Cause of Spill
 - ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
 - ☒ Operational Error ☒ Others (specify)
 - v. Visible Sign of Third Party Interference
 - ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
 - ☒ Others (specify)



6. Impact of Incident

i Properties impacted by the incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify)..... **NONE**

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others..... **NONE**

iii. Delineation of impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

i.
 ii. **N/A**
 iii.
 iv.

b) Land (indicate area in m²)

i.
 ii. **N/A**
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal



☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A	N/A	N/A

c) Swamp

☐ Tidal



☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			



d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

10. Samples taken..... NONE

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation. UNKNOWN PERSON(S) USED HACKSAW TO
CUT THE PIPELINE AT TWO DIFFERENT POINTS OF 0.7 METERS APART.

13. Time investigation ended.....