

PICTURES TAKEN AT SITE




SPILL POINT BEFORE EXCAVATION



SPILL POINT AFTER EXCAVATION



REPAIR WORK DONE BY NAOC REPAIR TEAM



TAPE RAPPING OF THE REPAIRED POINT