



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 23/08/2019 ii. Date first reported: 23/08/2019
 - iii. Date of first investigation: 24/08/2019 iv. Spill Incident No: 2019/SAR/033
 - v. Date of follow-up investigation:...../...../.....
 - vi. Time investigation started: 12:05 HRS
 - vii. Estimated quantity spilled(bbls): 0.002 viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: 24" OGDH/BRASS PIPELINE AT AGBANKBIRI/TD
 - ii. State: BAYELSA iii. L.G.A: NEMBE
 - iv. Spill Co-Ordinates: N(m) 04° 31' 31.3"
E(m) 006° 21' 56.0"
 - v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
 - iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
 - ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)
 - iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
 - iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
 - v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid _____
☒ Others (specify).....



6. Impact of Incident

i Properties impacted by the incident

- ☒Farmland ☒Fish Pond ☒Vegetation ☒Fishing Net ☒Surface water
☒Venerable Objects ☒Others (specify).....

ii. Nature of impact

- ☒Oil stained vegetation ☒Oil stained fishing nets ☒Dead floating fishes
☒Dead floating crabs ☒Withering of vegetation ☒Others.....

iii. Delineation of impacted area

- ☒Within Company’s facility/ROW ☐Outside Company’s facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops ☒Fish Farm/ Pond ☒Fishing Net ☒Makeshift
☒ Permanent ☒Others

8. Extent of Impact

a) Community (indicate name)

- i.
ii.
iii.
iv.

b) Land (indicate area in m²)

- i.
ii.
iii.
iv.

b) Creeks/Creek lets ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A			

c) Swamp ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A			

d) River ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A			

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A			

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation.

Nigerian Agip Oil Company should improve in their intervention cases so as to maintain environmental best practice and operations.

13. Time investigation ended.....

4:30 HRS