



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: Nigerian Pipelines and Storage Company Limited
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify): Oil Pipeline Vandalization / Fire explosion
3. Incident Details
i. Date of Incident: 27/01/2019 ii. Date first reported: 5/02/2019
iii. Date of first investigation: 8/2/2019
iv. Date of follow-up investigation: _____
v. Time investigation started: 12:15 hr
vi. Estimated quantity spilled: Not specified
4. Site Details
i. Site Location: Odi/fadiwo Village, Ogun State
ii. Position of Spill/Leak: Contained and the pipeline repaired
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify): _____
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify): Repaired
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
} Hole position
} not seen because
} repaired is already
} been done.
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products
☐ Others (specify): _____
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify): _____
iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify): _____
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify): We were told by NOSDRA staff that the line was vandalized but NOSDRA team did not see the section of pipeline because repairs are been done.

6. Impact of Incident

i. Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)

ii. Nature of impact

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others *burnt vegetation*

iii. Delineation of impacted area

☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i. *Od. / F.T.W.U*
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft




11. Remarks/Recommendation

The pipeline right of way patrol team advised to carry out regular and more vigilant monitoring of the pipeline

12. Time investigation ended 1300 hr

13. Name and Signature of Participants

❖ NOSDRA

1. UGWU BENJAMIN E. 
2. OMODIABAYE RICHARD U. 
3. Adedunm TUNY 
4. Idahor victor 

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY

1. UYEMALA M. ABIODUN
2. OKPOKIRI VINCENT
- 3.

❖ COMMUNITY

- 1.
- 2.