



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAD C

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 14/6/2019 ii. Date first reported: 14/6/2019
iii. Date of first investigation: 16-06-2019
iv. Date of follow-up investigation:
v. Time investigation started: 1:30 PM
vi. Estimated quantity spilled: 4.6 BBL

4. Site Details

- i. Site/Location: EBOTHA 5 WELL LOCATION @ OBBRIKOM
ii. Position of Spill/Leak: COLLAPSE EBOTHA 5 WELL PERIMETER FENCE

iii. Spill area

- ☒ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☐ Flow Line ☒ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify) REQUIRED WELL LOCATION

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) STRUCTURAL FAILURE

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) N/A

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. ADJOINED SEASONAL
ii. SWAMP AREA

(b) Land (Indicate area in m²)

i.
ii.
iii.
iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... CLEAN-UP IMPACTED AREA
AND BUILD THE STRUCTURE THAT FAILED

12. Time Investigation ended..... 3:05 PM

13. Name and Signature of Participants

❖ NOSDRA
1. AUGUSTINE BELLO *[Signature]* 16/6/2019

2.
3.

❖ DPR
1.
2.
3.

❖ STATE MINISTRY OF ENVIRONMENT
1. OGBURU, GP. IJEJE *[Signature]* 16/06/2019

❖ LOCAL GOVERNMENT COUNCIL
1.
2.
3.

❖ COMPANY
1. Ekelerehio, Ohere
2. OKAH KENNETH *[Signature]* NAOC (SxN) 16/06/2019
3. AMAZI NEWMAN - C. RIGGS *[Signature]* 16/06/2019

❖ COMMUNITY
1. CHRISTIAN F. UBI *[Signature]*
2. CHRISTOPHER OKIRIE *[Signature]* 08064041223
3. Ugoetukwu Thompson *[Signature]*
4. CHRISTIAN E. EKURU *[Signature]* 08663802999