




National Oil Spill Detection & Response Agency

FORM B

RISK BASED ASSESSMENT OF OIL SPILL INCIDENCE (RBA)

Note: This report must be submitted within 2 weeks of Spill Incidence

1. GENERAL INFORMATION:			
i. Company Name:	OVH ENERGY MARKETING LIMITED		
ii. Date of Assessment:	6TH - 8TH MARCH, 2019		
iii. Incident Details:	Date of Incidence (dd/mm/yy)	Date spill was stopped	Method Used
	06/03/19	20/11/18	☐ Clamping ☐ Well Shut-in ☐ Valve Shut-in ☐ F/Station Shut down ☒ Others (specify)..... ISOLATION OF LEAKING PORTION OF PIPELINE
iv. Estimated quantity spilled: 16,000 LITERS			
v. Estimated quantity recovered: 450 LITERS			
vi. Cause of Spill			
☒ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident ☐ Operational Error ☐ Others (specify)..... RESURFACE OF NOVEMBER 2018 AGO SPILL			
2. Site Details			
i. Site Name: NPA - Transit Trailer Park		OML:	
ii. GPS FIELD POINTS Total Length _____ m Length Surveyed _____ m Differential GPS Yes/No			
Spill Start Point GPS: EASTINGS 3° 21' 40.62" E _____ meters NOTINGS 6° 27' 35.00" N _____ meters			
Spill End Point GPS: EASTINGS 3° 21' 40.62" E _____ meters NOTINGS 6° 27' 34.99" N _____ meters			
iii. Site area			
☐ Land Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline ☐ Near Shore ☐ Offshore ☒ Others (Specify)..... NPA - Transit Trailer Park Premises			
iv. Facility			
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig ☐ Storage Tank ☐ Compressor Plant ☐ Others(Specify).....			
v. Site Characterization			
a. Sea Conditions			
☐ Calm ☐ Rough ☒ Not Applicable ☐ Low Tide ☐ High Tide			
Current direction:			
Swell Height:			
Current Strength:			
b. Weather Conditions			
☒ Bright Sunny ☐ Party Cloudy ☐ Slight rain ☐ Others (Specify).....			
Temperature: 38°C Wind Direction:			
Wind Speed: Relative Humidity:			
vi. Visual Observation of Impacted area			
(i) Any oil sheen on water	Yes	☐ No	☐ N/A ☒
(ii) Any oil sheen on water	Yes	☐ No	☐ N/A ☒
(iii) Any oil sheen on water	Yes	☐ No	☐ N/A ☒
(iv) Any oil sheen on water	Yes	☐ No	☐ N/A ☒
(v) Any oil sheen on water	Yes	☐ No	☐ N/A ☒



Receptor Assessment

Receptor	Pathway to Impacted Area(m ²)	Distance to Impacted Area(m ²)	Estimated Area of Impact Area(m ²)	Receptor Impacted (Yes/No)	Remarks
Farmland					
Fish Pond					
Vegetation					
Surface Water					
Ground Water					
Venerable Object					
Human Habitation					
Livestock					
Plantation					
Swamp					

vii. Any Casualties ☐ Yes ☒ No

If yes, give details.....

viii. Clean-up Program details


- a. Method of clean-up..... Bioremediation of the impacted area
- b. Time frame for clean-up..... 5 weeks and 3 days

ix. General Remarks

The area is relatively clean of spilled product. However, the clean up exercise will involve excavation of the impacted area to introduce Bioremediation reagents and the repair of the affected area - NPA Transit Trailer Park.

REPORTING OFFICER: UBONG AKPADIAHA

DESIGNATION: TERMINAL EHS SUPERVISOR

SIGNATURE: 

DATE: 04/09/2019

**Clean-up program report must be submitted within 2 weeks of spill incidence.*