



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

TOTAL E & P NIGERIA LIMITED

1. Company: .....

2. Type of Complaint/Incident:

☒ Oil Pollution

☐ Fire/Explosion

☐ Drilling Mud/Chemical Pollution

☐ Others (Specify) .....

3. Incident Details

i. Date of Incident: 29/09/19

ii. Date first reported: 29/09/19

iii. Date of first investigation: 30/09/2019

iv. Date of follow-up investigation: .....

v. Time investigation started: 1130 hrs

vi. Estimated quantity spilled: 30 Bbls

4. Site Details

i. Site/Location: 4" Flow Line @ Obobury Onelga

ii. Position of Spill/Leak: E 461388.02 N 137142.46

iii. Spill area

☒ Land

☐ Swamp

☐ Freshwater

☐ Mangrove

☐ Coastline

☐ Near shore

☐ Offshore

☐ Others (Specify) .....

iv. Structural Controls in Place

☐ Boom

☒ Trenches

☒ Bund Wall

☐ Sorbents

☐ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 0' Clock

☐ 10 0' Clock

☐ 2 0' Clock

☐ 3 0' Clock

☐ 4 0' Clock

☐ 5 0' Clock

☐ 6 0' Clock

ii. Type of Oil Contaminant

☒ Crude Oil

☐ Condensate

☐ Chemicals

☐ Refined Products

☐ Others (Specify) .....

iii. Facility

☐ Pipeline

☒ Flow Line

☐ Wellhead

☐ Manifold

☐ Flow Station

☐ Rig

☐ Storage Tank

☐ Compressor Plant

☐ Others (Specify) .....

iv. Cause of Spill

☐ Corrosion

☒ Equipment Failure

☐ Third Party Interference

☐ Accident

☐ Operational Error

☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks

☐ Drilled Holes

☐ Blasting

☐ Theft

☐ Acid

☐ Others (Specify) .....

Rupture on the flowline (4")