



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) GAS
3. Incident Details
i. Date of Incident: 30/05/19 ii. Date first reported: 30/05/2019
iii. Date of first investigation: 07/06/19 iv. Spill Incident No: 2019/SAR/GL/013
v. Date of follow-up investigation: N/A
vi. Time investigation started: 10:10 HRS
vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. Site Details
i. Site/Location: 6" TADMO - OGBOMBI GAS DELIVERY LINE @ KASSAMA
ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW LGA
iv. Spill Co-Ordinates: N(m) 04° 53' 01.8"
E(m) 005° 56' 47.4"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify)
vi. Structural Controls in Place
☒ Boom ☒ Fences ☒ Bund wall ☒ Sorbents ☒ Others (specify) N/A
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify) GAS
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)
iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify)
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify)



6. Impact of Incident

i. Properties impacted by the incident

☒ Farmland ☐ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify) N/A

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others H/A

iii. Delineation of impacted area

☒ Within Company's facility ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☒ Others N/A

8. Extent of Impact

a) Community (indicate name)

i.
 ii. N/A
 iii.
 iv.

b) Land (indicate area in m²)

i.
 ii. N/A
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal


☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

c) Swamp

☐ Tidal


☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken.....

NONE

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation

UNKNOWN PERSON(S) USED HACKSAW TO CUT THE LINE FROM 10 O'CLOCK POSITION TO 3 O'CLOCK POSITION AND USED EXPLOSIVE TO BLAST THE LINE OPEN.

13. Time investigation ended.....

16:50 HRS