


APPENDIX 1

The pipeline was severed into two by the blast.



Sectional replacement was carried out.



Repaired.

