

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company NIGERIA AGIP OIL COMPANY
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
 - ☒ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 29.09.2019 ii. Date first reported: 29/09/2019
 - iii. Date of first investigation: 02.10.2019 iv. Spill Incidence No: 2019/SAR/073
 - v. Date of follow-up investigation:
 - vi. Time investigation started: 12:16 HRS
 - vii. Estimated quantity spilled(bbls): 15BBLS viii. Quantity Recovered: 0-9BBL

4. Site Details
 - i. Site/Location: WELL 1 AND WELL 4 AT OKIAMA
 - ii. State: BAYELSA iii. LGA: NEMBE
 - iv. Spill Co-ordinates: N(m) WELL 1 N04° 36' 57.8" N04° 36' 57.8" WELL 4 N04° 36' 58.4"
E(m) WELL 1 E006° 11' 37.8" E006° 11' 37.8" E006° 11' 37.1"
 - v. Spill area
 - ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
 - ☒ Near shore ☒ Offshore ☒ Others (specify).....
 - vi. Structural Controls in Place
 - ☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
- Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
 - ☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
 - ☒ Others (specify).....
 - iii. Facility
 - ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
 - ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
 - iv. Cause Of Spill
 - ☒ Collision ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
 - ☒ Operational Error ☒ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☒ Flare Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
 - ☒ Others (specify).....



6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Nets
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify) _____

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others (Specify) _____

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

i. OKIAMA

i. 2,500M²

ii. _____

iii. _____

iv. _____

(c) Creek/Creek Lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water:

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation *Nigeria Agip Oil Company Should intensify Surveillance on its facilities and maintain environmental best Practices during operation.*

12. Time Investigation ended *12:40 HRS*