



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
 - ☒ Others (Specify) CONDENSATE & GAS EMISSION
3. Incident Details
 - i. Date of Incident: 17/09/2019 ii. Date first reported: 17/09/2019
 - iii. Date of first investigation: 25/09/2019 iv. Spill Incidence No: 2019/LAR/103 & 2019/LAR/GL1/034
 - v. Date of follow-up investigation: 26/09/2019
 - vi. Time investigation started: 13:10 HR & 15:30 HRS
 - vii. Estimated quantity spilled(bbls): 2 viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: 6" TUDMO-DGBDINBIRI GAS DELIVERY LINE AT OGROSUWARI
 - ii. State: BA/ELSA iii. L.G.A: EKEREMOR
 - iv. Spill Co-ordinates: N(m) 04° 57' 51.3" 04° 57' 52.2"
E(m) 005° 55' 58.8" 005° 55' 58.6"
 - v. Spill area
 - ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
 - ☒ Near shore ☒ Offshore ☒ Others (specify)
 - vi. Structural Controls in Place
 - ☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify)
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock 9° CLOCK ☒
 - ☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock 7° CLOCK ☒
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
 - ☒ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
 - ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)
 - iv. Cause Of Spill
 - ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
 - ☒ Operational Error ☒ Others (specify)
 - v. Visible Sign of Third Party Interference
 - ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
 - ☒ Others (specify)



6. Impact of Incident

i Properties impacted by the incident

- ☒Farmland ☒Fish Pond ☒Vegetation ☒Fishing Net ☒Surface water
☒Venerable Objects ☒Others (specify).....

ii. Nature of impact

- ☒Oil stained vegetation ☒Oil stained fishing nets ☒Dead floating fishes
☒Dead floating crabs ☒Withering of vegetation ☒Others.....

iii. Delineation of impacted area

- ☒Within Company’s facility/ROW ☒Outside Company’s facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i.
ii.
iii.
iv.

b) Land (indicate area in m²)

- i. 420.88
ii.
iii.
iv.

b) Creeks/Creek lets

- ☒Tidal ☒Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation. NAOC SHOULD DEPLOYED TECHNOLOGICAL APPROACH
IN MONITORING ITS FACILITY AND ALSO CLEAN-UP THE IMPACTED
AREA IMMEDIATELY.

12. Time Investigation ended..... 18:45 HRS