

PICTURES TAKEN AT SITE:



SPILL POINT BEFORE EXCAVATION



SPILL POINT AFTER EXCAVATION



REPAIR WORK DONE BY NAOC REPAIR TEAM



BACK FILLING OF SPILL POINT

RECOMMENDATIONS

- NAOC should intensify surveillance on its facility and maintain environmental best practices during operation.

Submitted for your consideration and further actions.

10