



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: CHEVRON NIGERIA LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 28TH SEPT, 2019 ii. Date first reported: 28TH SEPT, 2019
iii. Date of first investigation: 29TH SEPT 2019 iv. Spill Incident No.: 059
v. Date of follow-up investigation: 06 / DECEMBER, 2019
vi. Time investigation started: 10:00 AM
vii. Estimated quantity spilled (bbls): ±2 BBL viii. Quantity Recovered:.....

4. Site Details

- i. Site/Location: CHEVRON 18" DIBI-ABITEYE PIPELINE @ DIBI - FIELD COMMUNITY
ii. State: DELTA iii. L.G.A.:.....
iv. Spill Co-Ordinates: N(m) 05° 47.0' 11.0"
E(m) 005° 11.0' 48.0"
v. Spill area
☒ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock NOT - APPLICABLE

ii. Type of Oil contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)

iii. Facility

- ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☒ Others (specify) MYSTERY SPILL

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) NOT APPLICABLE



6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☒ Others (specify) SOIL

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☒ Others... SOIL

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others NOT APPLICABLE

8. Extent of Impact

a) Community (indicate name)

- i. DIBI - FIELD COMMUNITIES
 ii. _____
 iii. _____
 iv. _____

b) Land (indicate area in m²)

- i. _____
 ii. _____
 iii. _____
 iv. _____

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken... NONE

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation... CHEVRON SHOULD RECOVER FREE PHASE OIL, IMMEDIATE CLEAN UP IMPACTED SITES WHICH WILL BE MONITORED BY NOSDRA

13. Time investigation ended... 12:30pm

14. Name and Signature of Participants

❖ NOSDRA

1. OBI-IJEH - O - David [Signature] 06/12/2019
- 2.
- 3.

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ COMPANY

1. EKANEM SAMPSON [Signature] 06/12/19
2. OSAISAI TIMI [Signature] 06/12/19
3. L. JASIE [Signature] 06/12/19
4. A. Emegere [Signature] 6/12/19
- 5.

❖ COMMUNITY

- 08034814475 1. OGBURU. FRANCIS [Signature] 06/12/19
- 08161728876 2. Hon. Longbe Yeku [Signature] 6/12/19
- 08035724344 3. Gabriel Ekejor [Signature] 6/12/19
- 4.
- 5.