



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY

2. Type of Complaint/Incident:

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☒ Others (Specify).....

3. Incident Details

i. Date of Incident: 21 07 2019

ii. Date first reported: 21 07 2019

iii. Date of first investigation: 21 07 2019

iv. Spill Incident No: 2019/SAR/NL/013

v. Date of follow-up investigation: 14 50 HRS

vi. Time investigation started: 14:50 HRS

vii. Estimated quantity spilled(bbls): NIL

viii. Quantity Recovered: NIL

4. Site Details

i. Site/Location: 10" CLOUGH-CREEK @ AZAGBENE

ii. State: BAYELSA

iii. L.G.A: EKEREMOR

iv. Spill Co-Ordinates: N(m) 04° 49' 38.3"

E(m) 005° 42' 23.4"

v. Spill area

☐ Land

☒ Swamp

☐ Freshwater

☐ Mangrove

☐ Coastline

☐ Near shore

☐ Offshore

☐ Others (specify).....

iv. Structural Controls in Place

☐ Boom

☐ Trenches

☐ Bund wall

☐ Sorbents

☐ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock

☐ 10 O' Clock

☐ 2 O' Clock

☐ 3 O' Clock

☐ 4 O' Clock

☐ 5 O' Clock

☐ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil

☐ Condensate

☐ Chemicals

☐ Refined Products

☐ Others (specify).....

iii. Facility

☒ Pipeline

☐ Flow line

☐ Wellhead

☐ Manifold

☐ Flow Station

☐ Rig

☐ Storage Tank

☐ Compressor Plant

☐ Others (specify).....

iv. Cause of Spill

☐ Corrosion

☐ Equipment Failure

☒ Third Party Interference

☐ Accident

☐ Operational Error

☐ Others (specify).....

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks

☐ Drilled Holes

☐ Blasting

☐ Theft

☐ Acid

☒ Others (specify).....

Installed 3" Nipple



6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☒ Others (specify)..... NONE

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☒ Others... NONE

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. AZAGBENE
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii. 2612
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N/A</u>		

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N/A</u>		

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N/A</u>		

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N/A</u>		

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation. TIV was conclusive.
NAOC Should increase surveillance of her
facilities.

13. Time investigation ended.....