

SPDe2020-2709278



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

3. Incident Details

i. Date of Incident: 15-08-2020 ii. Date first reported: 15-08-2020

iii. Date of first investigation: 17-08-2020

iv. Date of follow-up investigation: .....

v. Time investigation started: 11:08 AM

vi. Estimated quantity spilled: 81 BBLs (RECOVERY TO THE VACUUM) (IMPACT AREA = 0.144 Ha) (TOTAL OIL = 6.2 BBLs) Command

4. Site Details

i. Site/Location: 12" INDIAN RIVER T-O GATE P/LINE @ OKOHTA, UTAH STATE

ii. Position of Spill/Leak: N 04° 55' 55.9" E 007° 11' 05.2"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline  
☐ Near shore ☐ Offshore ☐ Others (Specify) .....

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☒ Bund Wall ☐ Sorbents ☐ Others (Specify) BY LEE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0' Clock ☐ 10 0' Clock ☐ 2 0' Clock ☐ 3 0' Clock  
☐ 4 0' Clock ☐ 5 0' Clock ☐ 6 0' Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products  
☐ Others (Specify) .....

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig  
☐ Storage Tank ☐ Compressor Plant  
☐ Others (Specify) .....

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident  
☐ Operational Error ☐ Others (Specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid  
☐ Others (Specify) INSTALLATION OF LOCKING (IRON) FABRICATED CLAMP INSTALLED AT 12 0' CLOCK ON THE PIPE LINE BY UNIDENTIFIED PERSON