



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: TOTAL E&P

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

i. Date of Incident: 30-8-2020 ii. Date first reported: 30-8-2020

iii. Date of first investigation: 31-8-2020

iv. Date of follow-up investigation: 31-8-2020

v. Time investigation started: 12:50 PM

vi. Estimated quantity spilled: ~~65 bbl~~ 10.29 bbl Recovered 6.0 bbl

4. Site Details

i. Site/Location: KM 17.50 bagi - Rumekpe crude oil Export line @ Odigbe

ii. Position of Spill/Leak: 12:00 Clock

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
ii.
iii.
iv.

(b) Land (Indicate area in m²)

- i. 180 M²
ii.
iii.
iv.

(c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.. Increase surveillance on the pipeline
ROK1- clean-up the impacted area within the
regulatory time limit. Conduct Tier 2 Assessment to
ascertain level of groundwater contamination

12. Time Investigation ended..... 4:20 pm

13. Name and Signature of Participants

❖ NOSDRA

1. Augustine Bello ~~Bello~~ 31/8/2020
2.
3.

❖ DPR

1. Ummor, EMEKA BARNABAS 
2.
3.

❖ STATE MINISTRY OF ENVIRONMENT

1. OGBULU, GR. ISENE ~~Iseke~~ 31/08/2020
2.
3.

❖ LOCAL GOVERNMENT COUNCIL

1.
2.
3.

❖ COMPANY

1. Nnaemeka MBELE ~~MBELE~~ 31/08/2020
2.
3.

❖ COMMUNITY

1. Japhet ARWIKWA Odaje community 31/08/2020
2. Tebiah-m. Seti Odaje community 31/08/2020
3.