



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company NIGERIAN AGIP OIL COMPANY
2. Type of Complaint/Incident
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)
3. Incident Details
 - i. Date of Incident: 03.08.2019 ii. Date first reported: 03.08.2019
 - iii. Date of first investigation: 31.05.2020 iv. Spill Incident No: 2019/LAR/086
 - v. Date of follow-up investigation:
 - vi. Time investigation started: 14:45 HRS
 - vii. Estimated quantity spilled(bbls): 12.388 viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: TAYLOR GREEK 11, 2 L FLOW LINE IN KALABA COMM.
 - ii. State: BAYELSA iii. L.G.A: YENAGOA
 - iv. Spill Co-Ordinates: N(m) 05° 09' 02.7" N 05° 09' 02.7"
E(m) 006° 26' 29.0 E 006° 26' 29.3"
 - v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify)
 - iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify)
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock BLAST AT 12 O'clock
 - ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)
 - iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)
 - iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☐ Others (specify)
 - v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify)



6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☒ Others (specify)..... NIL

ii. Nature of impact

- ☒ Oil stained vegetation
☒ Oil stained fishing nets
☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others.... NIL

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
☒ Fish Farm/ Pond
☒ Fishing Net
☒ Makeshift
☒ Permanent
☐ Others NIL

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m^2)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/

9. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

10. Samples taken

11. Investigation carried out by

☒ Foot

☒ Boat

☐ Aircraft

12. Remarks/Recommendation

NADC SHOULD IMPROVE ON ITS
SURVEILLANCE AND SECURITY WITHIN AND OUTSIDE
THE ROW. (2) CLEAN-UP IS REQUIRED DUE TO THIS INCIDENT

13. Time investigation ended

15:35 HRS

14. Name and Signature of Participants