



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

85

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: IHS NIGERIA LTD

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 26-10-2019 ii. Date first reported:
iii. Date of first investigation: 20/12/2019
iv. Date of follow-up investigation:
v. Time investigation started: 11:59 HRS
vi. Estimated quantity spilled: 400 litres

4. Site Details

- I. Site/Location: IHS-OND-1021C
II. Position of Spill Leak: T15'42"N 5°9'35"E
III. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near Shore ☐ Offshore ☐ Others (Specify).....
IV. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbent ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

- i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
- ii. Type of Oil containment
☐ Crude Oil ☐ Condensate ☐ Chemical ☒ Refined Product
☒ Other (Specify) Diesel oil
- iii. Facility
☐ Pipeline ☐ Flow line ☐ wellhead ☐ Manifold ☐ Flow station ☐ Rig
☒ Storage Tank ☐ Compressor Plant ☐ Others (Specify)
- iv. Cause Of Spill
☐ Corrosion ☒ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)
- v. Visible Sign of Third Party Interference
☐ Hacksaw Mark ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) N/A