

STATE.



FIG. A: SHOWING 6" FLANGE INSTALLED ON THE PIPELINE BY UNKNOWN PERSON(S) FOR THEFT



FIG. B: SHOWING REPAIRED SECTION OF THE PIPELINE. FIG. C: SHOWING OIL BAILED FROM THE PIT