



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LIMITED (NAOC)
2. Type of Complaint/Incident:
☐ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 14/07/2021 ii. Date first reported: 14/07/2021
 - iii. Date of first investigation: 18/07/2021 iv. Spill Incident No.: 2021/SHR/043
 - v. Date of follow-up investigation: N/A
 - vi. Time investigation started: 14:39 HRS
 - vii. Estimated quantity spilled (bbls): 3 BBLs viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: 14" OGBOINBIRI ITERI DABA PIPELINE AT IKEBIRI
 - ii. State: BAYELSA iii. L.G.A.: SOUTHERN LGA
 - iv. Spill Co-Ordinates: N(m) 04° 40' 48.4"
E(m) 005° 57' 42.7"
 - v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
 - iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify) NONE
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
 - ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)
 - iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
 - iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
 - v. Visible Sign of Third Party Interference
☒ Jawsaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☐ Acid
☒ Others (specify) 6" FLANGE WAS INSTALLED AT 12 O' CLOCK POSITION BY UNKNOWN PERSON(S) FOR THEFT.



6. Impact of Incident

i. Properties impacted by the incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify) NONE

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others NIL

iii. Delineation of impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☐ Others NONE

8. Extent of Impact

a) Community (indicate name)

i. IKEBIRI

ii.

iii.

iv.

b) Land (indicate area in m²)

i. 150m²

ii.

iii.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken... N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation

NAOC SHOULD CARRY OUT CLEAN UP OF AFFECTED AREA
NAOC SHOULD INTENSIFY SURVEILLANCE ON ITS FACILITIES.

13. Time investigation ended... 16:00 HRS