



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution
 ☐ Fire/Explosion
 ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 10th August 2022
 ii. Date first reported: 10th August 2022
 iii. Date of first investigation: 10th August 2022
 iv. Date of follow-up investigation: Nil
 v. Time investigation started: 1300HR
 vi. Estimated quantity spilled: 4 BBLs

4. Site Details

- i. Site/Location: 24" OIL-Brass PIPELINE @ Ogon Community, Awele, Rivers State
 ii. Position of Spill/Leak: N 05° 06' 18.1" E 006° 34' 19.1"

iii. Spill area

- ☒ Land
 ☒ Swamp
 ☒ Freshwater
 ☒ Mangrove
 ☒ Coastline
☒ Near shore
☒ Offshore
☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom
 ☒ Trenches
 ☒ Bund Wall
 ☒ Sorbents
 ☒ Others (Specify) NONE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock
 ☒ 10 O'Clock
 ☒ 2 O'Clock
 ☒ 3 O'Clock
☒ 4 O'Clock
 ☒ 5 O'Clock
 ☒ 6 O'Clock
1-30' Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil
 ☒ Condensate
 ☒ Chemicals
 ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline
 ☒ Flow Line
 ☒ Wellhead
 ☒ Manifold
 ☒ Flow Station
 ☒ Rig
☒ Storage Tank
☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion
 ☒ Equipment Failure
 ☒ Third Party Interference
 ☒ Accident
☒ Operational Error
☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks
 ☒ Drilled Holes
 ☒ Blasting
 ☒ Theft
 ☒ Acid

o. impact or incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A	N/A	N/A	N/A

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A	N/A	N/A	N/A

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A	N/A	N/A	N/A

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A	N/A	N/A	N/A

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation... CLEAN-UP OF THE CRUDE IMPACTED AREA
SHOULD BE CARRIED OUT IMMEDIATELY.
THE COMPANY SHOULD INCREASE SURVEILLANCE ALONG THEIR
FACILITY.

12. Time Investigation ended... 1600HRS