

POST CLEAN UP JOINT INSPECTION REPORT

1.	SPILL REF. NO.:	2014/LAR/226/799		
2.	SPILL LOCATION:	OSHEIL f/L (IN AKINIMA)		
3.	CO-ORDINATES:	N050 06' 09.9" E006 28' 03.3"		
4.	DATE OF INSPECTION:	16-09-2015		
5.	SPILL DETAILS	DATE OF SPILL	CAUSE OF SPILL	QTY SPILLED
		13/11/14	SABOTAGE	9.4 BBLs
6.	DATE CLEAN UP COMMENCED:	06/08/15		
7.	CONTRACTOR:	BASIC NIG LTD		
8.	CONTRACT NO.:			
9.	CLEAN UP METHOD:	MECHANICAL ☐	MANUAL ☒	OTHERS ☒
	IF OTHERS, SPECIFY			
10.	NO. OF INCINERATION PITS:	N/A	STATE OF BURIED PITS.	N/A
11.	CLEAN UP DURATION	DATE CLEAN UP COMPLETED	TOTAL DURATION OF CLEAN UP	
		18/8/15	13 DAYS	
12.	ANY INCIDENT DURING CLEAN UP?	YES ☐	NO ☒	
	IF YES, WHAT TYPE			
13.	ANY CASUALTY/INJURY?	YES ☐	NO ☒	
	IF YES, HOW WAS IT MANAGED?			
14.	VISUAL OBSERVATIONS: (TICK AS APPROPRIATE)			
	ANY OIL SHEEN ON WATER?	YES ☐	NO ☒	NA ☐
	ANY OIL STAIN ON VEGETATION?	YES ☐	NO ☒	NA ☐
	IS SOIL WET WITH OIL?	YES ☐	NO ☒	NA ☐
	ANY PATCHES OF OIL ON IMPACTED AREA?	YES ☐	NO ☒	NA ☐
	IS DISPOSAL OF OIL DEBRIS SATISFACTORY?	YES ☒	NO ☐	NA ☐
	WAS DISPERSANT APPLIED?	YES ☐	NO ☒	NA ☐

14.	COMMUNITY ASSESSMENT:	VERY GOOD ☐	GOOD ☐	SATISFACTORY ☒	POOR ☐
15.	ANY SAMPLES COLLECTED?	YES ☒	NO ☐		
16.	IF YES, WHAT TYPE	SOIL ☒	WATER ☐		

17.	RECOMMENDATION:	Visually the site was properly cleaned and the site passed. However the close out will be determine by the result of samples collected for Laboratory Analysis

18.	CONCLUSION (INDICATE WHETHER CLEAN UP IS CERTIFIED AS):	SATISFACTORILY ☒	NOT SATISFACTORY ☐	POOR ☐
-----	---	--	---	-------------------------------