



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC) LTD.

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify).....

3. Incident Details

i. Date of Incident: 09/08/22 ii. Date first reported: 09/08/22

iii. Date of first investigation: 09/08/22 iv. Spill Incident No.: 2022/SAR/076

v. Date of follow-up investigation: -/-/-

vi. Time investigation started: 1420 HRS

vii. Estimated quantity spilled(bbls): 10 viii. Quantity Recovered: 2

4. Site Details

i. Site/Location: 14' OGBONBIRI/TEBIDABA P/L @ IKENBIRI

ii. State: BAJELSA iii. L.G.A.: SOUTHERN IDAW

iv. Spill Co-Ordinates: N(m) 04° 43' 19.3"
E(m) 005° 58' 18.7"

v. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (specify).....

iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock

☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☐ Others (specify)

iii. Facility

☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....

iv. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (specify).....

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☐ Acid

☒ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

Contractor:

☒ Farmland ☒ Fish Pond ☐ Vegetation ☒ Fishing Net ☐ Surface water

Signature: _____

☒ Venerable Objects ☒ Others (specify) NOT APPLICABLE

ii. Nature of impact

Name (printed): _____

☐ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes

Title: _____

☐ Dead floating crabs ☒ Withering of vegetation ☒ Others N/A

Date: _____

iii. Delineation of impacted area

☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift

☒ Permanent ☒ Others NOT APPLICABLE

8. Extent of Impact

a) Community (indicate name)

- i. _____
ii. _____
iii. _____
iv. _____

b) Land (indicate area in m²)

- i. _____
ii. _____
iii. _____
iv. _____

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... NOT APPLICABLE.....

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation. 2" FLANGE VALVE WAS INSTALLED
ON FACILITY AT 12 O'CLOCK POSITION FOR
OIL THEFT ACTIVITY. CLEAN-UP IS REQUIRED.

13. Time investigation ended.....