

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY
2. Type of Complaint/Incident:
- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
- ☒ Others (Specify) CONDENSATE
3. Incident Details
- i. Date of Incident: 17/02/2022 ii. Date first reported: 17/02/2022
- iii. Date of first investigation: 18/02/2022 iv. Spill Incident No.: 2022/SL/KAR/002
- v. Date of follow-up investigation:
- vi. Time investigation started: 14:48 HRS
- vii. Estimated quantity spilled(bbls): N/A viii. Quantity Recovered: N/A
4. Site Details
- i. Site/Location: 6" TUMOF OGBOUNBIRI GAS DELIVERY LINE @ AYANMASHI
- ii. State: BAYELSA iii. L.G.A: KEREMOR
- iv. Spill Co-Ordinates: N(m) 05° 06' 08.0"
- E(m) 005° 54' 38.6"
- v. Spill area
- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
- ☒ Near shore ☒ Offshore ☒ Others (specify) SEASONAL SWAMP
- iv. Structural Controls in Place
- ☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify)
5. Circumstances Around Spill Point
- i. Visual observation of Hole Position
- ☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
- ☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
- ii. Type of Oil contaminant
- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
- ☒ Others (specify)
- iii. Facility
- ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
- ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify) DELIVERY LINE
- iv. Cause of Spill
- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
- ☒ Operational Error ☐ Others (specify)
- v. Visible Sign of Third Party Interference
- ☒ Hack saw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
- ☐ Others (specify)

6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
 ☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
 ☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☒ Fishing Net
 ☒ Makeshift
 ☒ Permanent
 ☒ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken.....

N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation.....

13. Time investigation ended.....

14. Name and Signature of Participants

❖ NOSDRA

1. GODBLESS KUROK ECHIA IKO1 ~~Signature~~ 19/02/2022
- 2.
- 3.

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ COMPANY

1. JOHNSON LUCKY NAOC HSE ~~Signature~~ 19/02/22
2. C. N. AGUWE NAOC STD ~~Signature~~ 19/02/22
- 3.
- 4.
- 5.

❖ COMMUNITY

1. RICHMAN OKOYI. (AYAMASA CDC CHAIRMAN) ~~Signature~~ 19/2/22
- 2.
- 3.