



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) CONDENSATE

3. Incident Details

- i. Date of Incident: 14 / 12 / 2021 ii. Date first reported: 14 / 12 / 2021
iii. Date of first investigation: 18 Dec 2021 iv. Spill Incident No.: 2022/LAR/024
v. Date of follow-up investigation: 19 FEB 2022
vi. Time investigation started: 1201 HRS
vii. Estimated quantity spilled(bbls): 0.5 bbl viii. Quantity Recovered: NIL

4. Site Details

- i. Site/Location: 6th TUNO/OTBOWBURI REPERING AT OTBOSUWARI
ii. State: BAYELSA iii. L.G.A.: SKKREMOR
iv. Spill Co-Ordinates: N(m) 04° 58' 34.0"
E(m) 005° 55' 52.3"

v. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify) SEASONAL SWAMP

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify) PIT

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)

iii. Facility

- ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☒ Jacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify) 2" BALL VALVE AND PIPE CONNECTION ON THE
FAULTY.



6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
 ☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
 ☒ Dead floating crabs
 ☒ Withering of vegetation
 ☐ Others... WAT SAL DEBROS

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☒ Fishing Net
 ☒ Makeshift
 ☒ Permanent
 ☒ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii. OUBOSUNARI
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii. 28,39m²
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal
 ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal
 ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal
 ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken.....

N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation.....


CLEAN-UP SHOULD BE CARRIED OUT.

13. Time investigation ended.....

3:26 pm

14. Name and Signature of Participants

❖ NOSDRA

1. GODBLESS KUROKEGHA IKOI  28/02/2022
- 2.
- 3.




❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ COMPANY

1. JOHNSON LUCKY NAOC HSE-ENV  28/02/2022
2. C. N. ADUWE NAOC SYD  28/02/2022
3. OZZO G. I NAOC-ENV  28/02/2022
- 4.
- 5.