



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NERERIA AGIP OIL COMPANY LIMITED
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)
3. Incident Details
i. Date of Incident: 12/09/2021 ii. Date first reported: 12/09/2021
iii. Date of first investigation: 25/09/21 iv. Spill Incident No.: 2021/LAR/NLI/035
v. Date of follow-up investigation: N/A
vi. Time investigation started: 1357 HRS
vii. Estimated quantity spilled(bbls): Nil viii. Quantity Recovered: N/A
4. Site Details
i. Site/Location: 6" TUOMO-ONBAINBIRI PIPELINE AT AYAMASA
ii. State: BAYELSA iii. L.G.A: RKEREKOR
iv. Spill Co-Ordinates: N(m) N 05° 06' 43.1"
E(m) E 005° 54' 32.7"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify) SEASONAL SWAMP
- iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify)
5. Circumstances Around Spill Point
i. Visual observation of Hole Position 7 o'clock
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☐ 6 O' Clock
- ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)
- iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)
- iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify) OIL THEFT (SABOTAGE)
- v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify) 2" NIPPLE WAS INSTALLED ON THE FACILITY AT 7 O'clock.



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☒ Fishing Net
 ☒ Makeshift
☒ Permanent
☒ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii. AYANASA
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii. N/A
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N</u>	<u>A</u>	

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N</u>	<u>A</u>	

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N</u>	<u>A</u>	

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N</u>	<u>A</u>	

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken... N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation.....

13. Time investigation ended... 1540 HRS

14. Name and Signature of Participants

❖ NOSDRA

1. GODBLESS KUROKORHA IKOI

2.

3.

[Signature] 25/09/2021

❖ DPR

1.

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1. JOSEPH EBHON

2.

3.

Ace 25/09/2021

❖ COMPANY

1.

2.

3.

4.

5.

❖ COMMUNITY

1. OKOTI RICHMAN BOMIEGTON

2.

3.

[Signature]