



Figure 1. installed valve



Figure 2. okoron Riser

Missing
bolt



Hacksaw cut

Figure 3. Hacksaw cut on the pipeline