



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LTD

2. Type of Complaint/Incident:

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify).....

3. Incident Details

i. Date of Incident: 05/02/2022 ii. Date first reported: 05/02/2022

iii. Date of first investigation: 05/02/2022 iv. Spill Incident No: 2022/SAR/NL/002

v. Date of follow-up investigation:...../...../.....

vi. Time investigation started: 11:59 AM

vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL

4. Site Details

i. Site/Location: 18" TEBADABE/BRASS PIPELINE AT OYEREGBENE

ii. State: BAYELSA iii. L.G.A: SOUTHERN ITAW

iv. Spill Co-Ordinates: N(m) 04° 29' 34"
E(m) 006° 04' 59.5"

v. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....

iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock

☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (specify)

iii. Facility

☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....

iv. Cause of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (specify).....

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (specify).....

6. Impact of Incident**i Properties impacted by the incident**

- ☐ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
 ☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
 ☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☒ Fishing Net
 ☒ Makeshift
 ☒ Permanent
 ☒ Others

8. Extent of Impact**a) Community (indicate name)**

- i. DYERE GBENE
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

☒ Still photographs

☐ Video coverage

☐ Mapping

60

10. Samples taken.....

11. Investigation carried out by

☐ Foot

☒ Boat

☐ Aircraft

12. Remarks/Recommendation CLEANING OF THE COMPANY RIGHT
OF WAY. JSD DEBRIS/SECURITATION COMPLETED ON
THE 05/02/2022. NO CLEAN-UP AS THERE WAS NO DEBRIS

13. Time investigation ended 4:25 PM

14. Name and Signature of Participants

❖ NOSDRA

1. WILSON BOON EKECH 05/02/2022
- 2.
- 3.

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

1. ROLAND IBERU
- 2.
- 3.

05/02/2022

❖ COMPANY

1. Engr Charles NAOC CRV 05/02/2022
2. OMONGO MIKE NAOC HSE 05/02/2022
3. Omorodion Eddy Surveyor 05/02/2022
- 4.
- 5.