



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN ALUP OIL COMPANY LTD

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 04/07/2021 ii. Date first reported: 04/07/2021
iii. Date of first investigation: 04/07/2021 iv. Spill Incident No.: 2021/SAR/037
v. Date of follow-up investigation: 05/07/2021
vi. Time investigation started: 8:24 AM
vii. Estimated quantity spilled (bbls): 1566 viii. Quantity Recovered: nil

4. Site Details

- i. Site location: 18" TEB, BABA/GRASS PIPELINE AT LASUKU GBENSE
ii. State: BATELSA iii. L.G.A.: SOUTHERN ISAW
iv. Spill Co-Ordinates: N(m) 04° 30' 18.9"
E(m) 006° 03' 20.9"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
vi. Spill Control Measures in Place
☒ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify).....

iii. Facility


- ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause of Spill

- ☐ Collision ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Occupational Peril ☐ Others (specify).....

v. Visible Sign of Third Party Interference

- ☒ Drifted Logs ☐ Drilled Holes ☐ Blasting ☐ Theft ☒ Acid
☐ Others (specify).....



6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. LASUKU CRENE
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 8,083.97 m²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation THE IMPACTED AREA SHOULD BE CLEANED. SECURITY SERVICES SHOULD ALSO BE IMPROVED.

13. Time investigation ended... 15:05 PM

14. Name and Signature of Participants

❖ NOSDRA

1. UHAM, BON ERUP

[Signature] 05/07/2021

2.

3.

❖ DPR

1.

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1. ROWLAND IBEFU

[Signature] 5/07/21

2.

3.

❖ COMPANY

1. AGBAKURIBE Emma SACR CRU [Signature] 05/07/21

2. OMONGO MIKE NAOC HSE [Signature] 5/7/2021

3. MIBEMA ODISHIOYE SURVEYOR 5/7/2021

4.

5.