



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGRI OIL COMPANY LTD
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 02/07/2021 ii. Date first reported: 02/07/2021
 - iii. Date of first investigation: 02/07/2021 iv. Spill Incident No: 2021/SAR/1032
 - v. Date of follow-up investigation: /
 - vi. Time investigation started: 11:33AM - 2:50pm
 - vii. Estimated quantity spilled(bbls): 3 bbls viii. Quantity Recovered: NIL
4. Site Details
 - i. Site Location: 18' IEBIABA / BIAH PIPELINE AT BEBARA
 - ii. State: DELTA iii. L.G.A: SOUTHERN OIAW
 - iv. Spill Co-Ordinates: N(m) 04° 30' 43.31"
E(m) 006° 01' 54.91"
 - v. Spill area
 - ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify).....
 - vi. Environmental controls in Place
 - ☒ Boom ☐ Silt fences ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☐ 12 O' Clock ☒ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Contaminant
 - ☒ Crude oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify).....
 - iii. Facility
 - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. Cause of Spill
 - ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
 - ☐ Operator Error ☐ Others (specify).....
 - v. Visible Signs of Third Party Interference
 - ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
 - ☐ Others (specify).....



6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. BEBARA CIBENE
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 5,762-28m²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation MAINTENANCE OF THE FACILITY ROUGH
OF WAY: IMPACTED AREAS SHOULD BE CLEARED
IMPROVE ON SECURITY SERVICES

13. Time investigation ended 14:50 PM.

14. Name and Signature of Participants

❖ NOSDRA

1. UKAM, IBON EKUP
- 2.
- 3.

02/07/2021

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

1. PREYE ATIEGHA
- 2.
- 3.

02/07/2021

❖ COMPANY

1. AGBANKURIBE EMMA DACC CRV 2/7/21
2. OMONGO MIKE NAOC HSE 2/7/2021
3. MIDEMA ODIGHIOYE SURVEYOR 2/7/2021
- 4.