



1. Company: NIGERIA AGIP OIL COMPANY (NAOC) LIMITED

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....

i. Date of Incident: 18/09/2022 ii. Date first reported: 18/09/2022
iii. Date of first investigation: 19/09/2022 iv. Spill Incident No.: 2022/SAR/104
v. Date of follow-up investigation: / /
vi. Time investigation started: 11:06 HRS
vii. Estimated quantity spilled(bbls): 150 BBLS viii. Quantity Recovered: RECOVERED ONGOING

i. Site/Location: 18' UBAMA/BRASS PIPELINE AT TEREKE
ii. State: BAYELSA iii. L.G.A: NEMBE
iv. Spill Co-Ordinates: N(m) 04° 24' 37.3"
E(m) 006° 16' 34.3"

- v. **Spill area**
- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
- ☒ Near shore ☒ Offshore ☒ Others (specify).....

☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....

i. Visual observation of Hole Position

- ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

A BLAST ON THE RISE

ii. Type of Oil contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)

iii. Facility

- ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify) THIRD PARTY USED AN EXPLOSIVE DEVICE
TO VANDALISE THE PIPELINE



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☒ Fishing Net
 ☒ Makeshift
☒ Permanent
☒ Others WATER BODIES

8. Extent of Impact

a) Community (indicate name)

- i. IEREKE
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 62,267.6270 m²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation..... SURVEILLANCE AND SECURITY
BOTH WITHIN AND OUTSIDE THE COMPANY'S ROW SHOULD
BE ENHANCED

13. Time investigation ended.....