



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NPSC NASIMI DEPOT
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 27/01/23 ii. Date first reported: 29/03/23
 - iii. Date of first investigation: 09/10/23
 - iv. Date of follow-up investigation: N/A
 - v. Time investigation started: 1211 Hours
 - vi. Estimated quantity spilled: Not yet quantified
4. Site Details
 - i. Site/Location: NASIMI DEPOT
 - ii. Position of Spill/Leak:
 - iii. Spill area
 - ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify).....
 - iv. Structural Controls in Place
 - ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify)..... N/A
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products
 - ☐ Others (specify)
 - iii. Facility
 - ☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☒ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. Cause Of Spill
 - ☐ Corrosion ☒ Equipment Failure ☐ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
 - ☐ Others (specify)..... N/A



6. Impact of Incident

i Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

☐ Venerable Objects ☐ Others (specify)..... *Groundwater*

ii. Nature of impact

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☐ Others..... *Groundwater*

iii. Delineation of impacted area

☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

N/A

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

i.

i.

ii. *N/A*

ii. *N/A*

iii.

iii.

iv.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<i>N/A</i>		

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<i>N/A</i>		

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<i>N/A</i>		

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<i>N/A</i>		

8. Photograph/Map/Chart Ref.

☐ Still photographs ☐ Video coverage ☐ Mapping

N/A

9. Samples taken.....

YES

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

Suspected storage tanks have been emptied for rehabilitation while borehole are currently clean by physical inspection

12. Time investigation ended.....

13. Name and Signature of Participants

❖ NOSDRA

1. Badmus Oladipo
2. Adamu Alakirao
3. Bawa Damilola Aliobun

❖ DPR

- 1.
- 2.
- 3.

N/A

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

N/A

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

N/A

❖ COMPANY

NPSC

1. Uzor Chukunali
2. Asugbo I.E
3. Akanji O.T

05/10/2023

❖ COMMUNITY

- 1.
- 2.
- 3.

N/A