



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NNPC PIPELINES & STORAGE COMPANY LIMITED

2. Type of Complaint/Incident:

☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify).....

3. Incident Details

i. Date of Incident: 23/1/2024 ii. Date first reported: 29/1/2024

iii. Date of first investigation: 3/2/2024

iv. Date of follow-up investigation: N/A

v. Time investigation started: 11:15am

vi. Estimated quantity spilled: 1100 LITERS

4. Site Details

i. Site/Location: KM 180 (KPS89)

ii. Position of Spill/Leak: N11°38'09.5", E008°21'41.8"

iii. Spill area

☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (specify).....

iv. Structural Controls in Place

☐ Boom ☒ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify) LINING

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☒ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

ii. Type of Oil contaminant

☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify) ASPH AND WATER

iii. Facility

☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

iv. Cause Of Spill

☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☒ Accident
☐ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) N/A

6. Impact of Incident

i Properties impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify) ... N/A

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others ... N/A

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m^2)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... Immediate repair and clean up of the site is recommended.

12. Time investigation ended..... 4:10 PM

13. Name and Signature of Participants

❖ NOSDRA

1. EGUWU H. A. AD/HEAD KDZO 3rd Feb, 2024
2. MUHAMMAD A. BISHARA ACES/HEAD KNZO Bisha 3rd Feb, 2024
3. ISMAN AMINY MUSA ACES 3rd Feb 2024
4. MUHAMMED TIJANI AHMED PES 3rd FEB. 2024.

❖ DPR5 DAVID AMEH REIBEN SES 3/2/2024

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

1. ABBA ADAMU TAKAI (DEPC) 3/2/24
- 2.
- 3.

❖ NPSC/NNPCL
LOCAL GOVERNMENT COUNCIL

1. Shelm Ishige 3/02/24
2. Ibrahim Abdulmajid 03/02/24
3. Ushamm IBRAHIM 3/02/24

❖ COMPANY

1. GODCUFF ATINBOBIENEMI (BCL)
2. Just Tuguan (BCL)
3. Wilson Jech (BCL) 3/2/2024
4. Emmanuel UKPONG 08037823444 3/2/2024

❖ COMMUNITY

1. MUHAMMED SANI TUKUR VILLAGE HEAD GARUN MACEAN
2. SALIS TUKUR, WARD HEAD 08/30840577 3/2/2024
3. MAHIRU SANI WARD HEAD 070 265827507 3/2/2024