



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: Nigerian Pipelines and Storage Company (NPSC)
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 14th February, September, 2020 ii. Date first reported: 14th February, September, 2020
 - iii. Date of first investigation: 15-11-2023
 - iv. Date of follow-up investigation: 15-11-2023
 - v. Time investigation started: 1027 Hours
 - vi. Estimated quantity spilled:
4. Site Details
 - i. Site/Location: Kfarm Agbale - Chief Rotimi Williams
 - ii. Position of Spill/Leak: 12 0 clock
 - iii. Spill area
 - ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify).....
 - iv. Structural Controls in Place
 - ☐ Boom ☒ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O Clock ☐ 10 O Clock ☐ 2 O Clock ☐ 3 O Clock
 - ☐ 4 O Clock ☐ 5 O Clock ☐ 6 O Clock
 - ii. Type of Oil contaminant
 - ☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products
 - ☐ Others (specify).....
 - iii. Facility
 - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....

262

iv. Cause Of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others: No impact observed

iii. Delineation of impacted area

- ☒ Within Company s facility/ROW ☐ Outside Company s facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i.....
 ii.....
 iii.....
 iv.....

b) Land (indicate area in m²)

- i.....
 ii.....
 iii.....
 iv.....

b) Creeks/Creek lets

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation *Window of JIV was too long, therefore no visible impact of spill on environment was observed. Ensure that NOSDRA is timely informed for subsequent site assessment and JIVs.*

263

12. Time investigation ended.....1100 Hrs

13. Name and Signature of Participants

❖ NOSDRA

1. Adams Alarirawa per 
2. Paul, E. Uibr 
3. Usman Adegheniro 

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY NPSC/NNPCL

1. Jacob J. Gongden 
2. Okpokiri V 
3. Engr. Makinde, O. M 

❖ COMMUNITY

1. Chief Kennedy 
2. Diepango MacHarry 
- 3.