

2024-2212115



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: S.P.D.C

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) NON-LEAKING

3. Incident Details

- i. Date of Incident: 11-04-2024 ii. Date first reported: 12-04-2024
iii. Date of first investigation: 13-04-2024
iv. Date of follow-up investigation:
v. Time investigation started: 14:38 HRS
vi. Estimated quantity spilled: NON-LEAKING

4. Site Details

- i. Site/Location: 14" OILORDIA-KUMHYPE PIPELINE AT OSHI
COMMUNITY, ANTONIA WEST LGIA, R.I.S
ii. Position of Spill/Leak: N.S. 10450 E6.51013

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) NON-LEAKING

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock ☒ 9-11:30 O'Clock
POSITION

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) NON-LEAKING

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid

ABOUT 170MM HACKSAW CUT OBSERVED ON THE PIPELINE AT 9-11:30 O'CLOCK POSITION BY UNKNOWN PERSON(S).

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

- ☐
- Venerable Objects
- ☐
- Others (Specify)
- NON-LEAKING

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

- | | | |
|---------------------|-------------------------|--------------------------------------|
| Dead floating crabs | Withering of vegetation | Others (Specify) <u>fish killing</u> |
|---------------------|-------------------------|--------------------------------------|

iii. Delineation of Impacted area

- ☐
- Within Company's facility/ROW
- ☐
- Outside Company's facility/ROW

7. Extent of Impact

- (a) **Community** (*Indicate name*)

- (b) **Land** (*Indicate area in m²*)


- i.

- ii.

- iii.

- iv. iv.

- (c) **Creek/Creek lets** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			
			
			

- (d) **Swamp** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

- (e) **River** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

- (f) **Shoreline/water** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken... NO SAMPLES COLLECTED AT THE TIME OF INVESTIGATION.

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation... SPDC WAS MANIFESTED TO CARRY OUT REPAIRS ON THE LEAKS IN PROXIMITY OF THE PIPELINE AS SOON AS POSSIBLE. ALSO TO INTENSIFY SURVEILLANCE ON THE PIPELINE RIGHT OF WAY. (R)

12. Time Investigation ended

16:15 HRS