

2024/SAK/IN/040



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LIMITED (NADOC)

2. Type of Complaint/Incident:

- ☒ Oil Pollution
 ☒ Fire/Explosion
 ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) NON-LEAK

3. Incident Details

- i. Date of Incident: 09/05/2024 ii. Date first reported: 09/05/2024
 iii. Date of first investigation: 09/05/2024
 iv. Date of follow-up investigation: /
 v. Time investigation started: 10:00 HRS
 vi. Estimated quantity spilled: NON-LEAK

4. Site Details

- i. Site/Location: 18" OBAMA/BRASS PIPELINE AT GOLUBOKIRI
 ii. Position of Spill/Leak: N 04° 29' 59.9" E 006° 15' 25.7"

iii. Spill area

- ☒ Land
 ☒ Swamp
 ☒ Freshwater
 ☒ Mangrove
 ☒ Coastline
☒ Near shore
 ☒ Offshore
 ☒ Others (Specify).....

iv. Structural Controls in Place

- ☒ Boom
 ☒ Trenches
 ☒ Bund Wall
 ☒ Sorbents
 ☒ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock
 ☒ 10 O'Clock
 ☒ 2 O'Clock
 ☒ 3 O'Clock
☒ 4 O'Clock
 ☒ 5 O'Clock
 ☒ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil
 ☒ Condensate
 ☒ Chemicals
 ☒ Refined Products
☒ Others (Specify) NON-LEAK

iii. Facility

- ☒ Pipeline
 ☒ Flow Line
 ☒ Wellhead
 ☒ Manifold
 ☒ Flow Station
 ☒ Rig
☒ Storage Tank
 ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion
 ☒ Equipment Failure
 ☒ Third Party Interference
 ☒ Accident
☒ Operational Error
 ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks
 ☒ Drilled Holes
 ☒ Blasting
 ☒ Theft
 ☒ Acid
☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify) ... N/A

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others (Specify) ... N/A

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. GOLUBOKIRI

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. N/A

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation.....

NADC SHOULD PUT MORE EFFORT INTO PIPELINE SECURITY

12. Time Investigation ended..... 12:00 HRS