

2024/LAR/NLI/061



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: INDRAMA ELEME PETROCHEMICAL LIMITED

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) NON-GAS LEAK

3. Incident Details

- i. Date of Incident: 06-06-2024 ii. Date first reported:
iii. Date of first investigation: 06-06-2024
iv. Date of follow-up investigation:
v. Time investigation started: 12:47 PM
vi. Estimated quantity spilled: NON-GAS LEAK

4. Site Details

- i. Site/Location: 8° 08' 08" - INDRAMA (NLI) PIPELINE AT UBIMA COMMUNITY, ILIHARE KIN, KIS
ii. Position of Spill/Leak: N 05° 04' 47.4" E 006° 53' 45.3"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) NON-GAS LEAK

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid

2" BALL VALVE AND A 2" RISERS ON 12 O' CLOCK POSITION ON THE PIPE