

2024/1001911/029



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: INDORAMA-ELENE PETROLEUM COMPANY

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) GAS LEAK

3. Incident Details

- i. Date of Incident: 12-05-2024 ii. Date first reported: 12-05-2024
iii. Date of first investigation: 13-05-2024
iv. Date of follow-up investigation: _____
v. Time investigation started: 11:05 PM
vi. Estimated quantity spilled: N/A

4. Site Details

- i. Site/Location: 8° 08' 08" - INDORAMA (PHI) PIPELINE AT OMEREN COMMUNITY
ii. Position of Spill/Leak: N 05° 12' 55.9" E 006° 50' 09.1"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify) _____

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) GAS LEAK

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify) _____

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
2" BALL VALVE WITH 3" STEEL PIPE CONNECTED
ON THE PIPELINE AT 12 O'CLOCK POSITION
BY UNKNOWN PERSON(S).

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) Nil

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
Dead floating crabs Withering of vegetation Others (Specify) red tide

iii. Delineation of Impacted area

- ☒
- Within Company's facility/ROW
- ☐
- Outside Company's facility/ROW









7. Extent of Impact

- (a) Community (Indicate name)


- (b) Land (Indicate area in
- m^2
-)

- i.
- ii.
- iii.
- iv.
- i.
- ii.
- iii.
- iv.


- (c) Creek/Creek lets
- ☐
- Tidal
- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			
			
			
			



- (d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

- (e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

- (f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

101 2-7

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken. NO SAMPLES COLLECTED AT THE TIME OF J-1

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. Report carried out immediately
after J-1 exercise. Surveillance should be
intensified on the pipeline Right of way (ROW)

12. Time Investigation ended. 2:15 PM